



Notes:

- Manufactured as one piece then cut apart to create the two part clamp, gap size not critical
- All three screw holes drilled 0.200" from bottom, outer two through and middle just over halfway (1.0")
- Holes in upper block drilled to 0.265 after the blocks are cut apart
- Holes in lower block tapped for 1/4"-20 after blocks are cut apart

ST-i Mount

Mount for an SBIG ST-i Camera

Andrew Cooper | Sep 2015 Page 1